

I think RM-10412 is far too vague to implement. It assumes field repair could be accomplished by people of unknown skill with unknown tools and unknown repair parts. Modern communications equipment manufactured with surface mount technology and automated testing and calibration is not feasible for field repair. As an alternative, a special piece of equipment could be offered with replacement modules for that application.

Sincerely, Fred C. Kelly III K8AWF